

ACU-RITE

Digital Readouts for Lathes, Mills, Grinders

New 200s Package



Bright LCD display
2 or 3 Axis
Bolt hole patterns
(linear & circular)
Centerline calculation
16 tool offsets/diameter
Preset and zero reset
Near zero warning


mm/inch switching
Error compensation
Edge finder input ready
Position-trac
(memory after power loss)
Absolute or incremental
Calculator / taper calculator

100s Package



1, 2, or 3 axis display
Bolt hole patterns
(linear & circular)
Centerline calculation
Preset and zero reset
mm/inch switching

Error compensation
Position-trac
(memory after power loss)
Absolute or incremental
Calculator



200S Lathe Packages

8" x 28"	thru	8" x 65"
10" x 36"	thru	10" x 120"
12" x 40"	thru	12" x 120"
14" x 40"	thru	14" x 120"
16" x 60"	thru	16" x 120"

200S Mill Packages

12" x 24"	thru	12" x 36"
13" x 32"	thru	13" x 36"
14" x 30"	thru	14" x 36"
16" x 30"	thru	16" x 36"
18" x 35"	thru	18" x 42"

100S Lathe Packages

8" x 28"	thru	8" x 65"
10" x 36"	thru	10" x 120"
12" x 40"	thru	12" x 120"
14" x 40"	thru	14" x 120"
16" x 60"	thru	16" x 120"

100S Mill Packages

8" x 18"		
10" x 20"		
13" x 32"	13" x 35"	13" x 36"
16" x 32"	16" x 35"	16" x 36"

ALL KITS INCLUDE:

Display, glass scales, armored cables, mounting bracket kit, display arm & tray kit